

DAMAGEABILITY TESTS OF MINICARS RSV

R. Garn
S. Davis

Dynamic Science, Inc.
A Talley Industries Company
1850 West Pinnacle Peak Road
Phoenix, Arizona 85027



Contract No. DTNH22-80-C-07694
Contract Amt. \$20,190



DECEMBER 1980
FINAL REPORT

This document is available to the U.S. public through the
National Technical Information Service,
Springfield, Virginia 22161

Prepared For
U.S. DEPARTMENT OF TRANSPORTATION
National Highway Traffic Safety Administration
Washington, D.C. 20590

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for its contents or use thereof.

TL
242
.637

TECHNICAL REPORT STANDARD TITLE PAGE

1. Report No. DOT-HS-805-770		2. Government Accession No.		3. Recipient's Catalog No.	
4. Title and Subtitle ✓ DAMAGEABILITY TESTS OF MINICARS RSV				5. Report Date December 1980	
				6. Performing Orgn Code	
7. Author(s) R. Garn, S. Davis				8. Performing Orgn Rpt No. 8342-80-168A	
9. Performing Organization Name and Address Dynamic Science, Inc. A Talley Industries Company 1850 West Pinnacle Peak Road Phoenix, Arizona 85027				10. Work Unit No. Research Operations	
				11. Contract or Grant No. DTNH22-80-C-07694	
12. Sponsoring Agency Name and Address U.S. Department of Transportation National Highway Traffic Safety Administration 400 Seventh Street, S.W. Washington, D.C. 20590				13. Type of Report and Period Covered FINAL REPORT August - September 1980	
				14. Sponsoring Agency Code	
15. Supplementary Notes					
16. Abstract This document presents the results of a series of vehicle-to-vehicle and vehicle-to-fixed barrier low speed impact tests. These tests were conducted utilizing specially constructed Research Safety Vehicles (RSV) prepared by Minicars, Inc. of Goleta, California. The test program was structured to evaluate the damageability of the vehicle designs.					
17. Key Words RSV, Head-On Barrier Impact, Side Impact, Front-to-Rear Impact				18. Distribution Statement This document is available to the public through the National Technical Information Service, Springfield, Virginia 22161	
19. Security Classif. (of this report) Unclassified		20. Security Classif. (of this page) Unclassified		21. No. Pages 54	
22. Price					

DEPARTMENT OF TRANSPORTATION
MAY 19 1981
LIBRARY

METRIC CONVERSION FACTORS

Approximate Conversions to Metric Measures

Symbol	When You Know	Multiply by	To Find	Symbol
LENGTH				
in	inches	2.5	centimeters	cm
ft	feet	30	centimeters	cm
yd	yards	0.9	meters	m
mi	miles	1.6	kilometers	km
AREA				
sq in	square inches	6.5	square centimeters	cm ²
sq ft	square feet	0.09	square meters	m ²
sq yd	square yards	0.8	square meters	m ²
sq mi	square miles	2.6	square kilometers	km ²
acres	acres	0.4	hectares	ha
MASS (weight)				
oz	ounces	28	grams	g
lb	pounds short tons (2000 lb)	0.45 9.1	kilograms tonnes	kg t
VOLUME				
teaspoon	teaspoons	5	milliliters	ml
Tablespoon	tablespoons	16	milliliters	ml
fl oz	fluid ounces	30	milliliters	ml
c	cups	0.24	liters	l
pt	pints	0.47	liters	l
qt	quarts	0.95	liters	l
gal	gallons	3.8	liters	l
cu ft	cubic feet	0.03	cubic meters	m ³
cu yd	cubic yards	0.76	cubic meters	m ³
TEMPERATURE (exact)				
°F	Fahrenheit temperature	5/9 (after subtracting 32)	Celsius temperature	°C

Approximate Conversions from Metric Measures

Symbol	When You Know	Multiply by	To Find	Symbol
LENGTH				
mm	millimeters	0.04	inches	in
cm	centimeters	0.4	inches	in
m	meters	3.3	feet	ft
km	kilometers	1.1	yards	yd
mi	miles	0.6	miles	mi
AREA				
sq cm	square centimeters	0.15	square inches	sq in
sq m	square meters	1.2	square yards	sq yd
sq km	square kilometers	0.4	square miles	sq mi
ha	hectares (10,000 m ²)	2.5	acres	acres
MASS (weight)				
g	grams	0.035	ounces	oz
kg	kilograms	2.2	pounds	lb
t	tonnes (1000 kg)	1.1	short tons	short tons
VOLUME				
ml	milliliters	0.03	fluid ounces	fl oz
l	liters	2.1	pints	pt
l	liters	1.06	quarts	qt
l	liters	0.26	gallons	gal
m ³	cubic meters	35	cubic feet	cu ft
m ³	cubic meters	1.3	cubic yards	cu yd
TEMPERATURE (exact)				
°C	Celsius temperature	9/5 (then add 32)	Fahrenheit temperature	°F



* 1 in = 2.54 (exactly). For other exact conversions, and more detailed tables, see NBS Spec. Publ. 285, Units of Weight and Measure, Price \$1.25, SD Catalog No. C13.10286.

TABLE OF CONTENTS

	<u>Page</u>
1.0 INTRODUCTION	1
2.0 PURPOSE	1
3.0 METHODOLOGY	1
4.0 DATA ACQUISITION	4
4.1 VEHICLE LOG	4
4.2 PHYSICAL MEASUREMENTS	4
4.3 PHOTOGRAPHY REQUIREMENTS	4
4.4 VEHICLE DAMAGE APPRAISALS	8
5.0 TEST RESULTS	8
5.1 TEST NO. 1: M5-10 FRONT-INTO-M5-11 REAR (12.5 MPH)	9
5.1.1 Post-test Dimensional Measurements	9
5.1.2 Post-test Observations	9
5.2 TEST NO. 2: M5-10 FRONT-INTO-M5-11 REAR (15.0 MPH)	10
5.2.1 Post-test Dimensional Measurements	10
5.2.2 Post-test Observations	10
5.3 TEST NO. 3: M5-10 FRONT-INTO-CHEVROLET CITATION REAR (15.0 MPH)	11
5.3.1 Post-test Dimensional Measurements	11
5.3.2 Post-test Observations	12
5.4 TEST NO. 4: M5-10 FRONT-INTO-CHEVROLET CITATION LEFT SIDE (5.0 MPH)	13
5.4.1 Post-test Dimensional Measurements	13
5.4.2 Post-test Observations	13
5.5 TEST NO. 5: M5-10 FRONT-INTO-M5-11 LEFT SIDE (5.0 MPH)	14

TABLE OF CONTENTS (CONTD)

	<u>Page</u>
5.5.1 Post-test Dimensional Measurements	14
5.5.2 Post-test Observations	14
5.6 TEST NO. 6: M5-10 FRONT-INTO-FIXED BARRIER (8.0 MPH)	15
5.6.1 Post-test Dimensional Measurements	15
5.6.2 Post-test Observations (M5-10 Vehicle)	15
5.7 TEST NO. 7: M5-10 FRONT-INTO-FIXED BARRIER (17.0 MPH)	15
5.7.1 Post-test Dimensional Measurements	16
5.7.2 Post-test Observations (M5-10 Vehicle)	16
APPENDIX A - VEHICLE PREPARATION AND TESTING LOG	A-1
APPENDIX B - CHEVROLET CITATION DAMAGE APPRAISALS	B-1
APPENDIX C - TEST SERIES PHOTOGRAPHS	C-1

1.0 INTRODUCTION

This report presents the results of a series of vehicle-to-vehicle and vehicle-to-fixed barrier low-speed impact tests. These tests were sponsored by the National Highway Traffic Safety Administration under Contract No. DTNH22-80-C-07694. A total of seven separate tests were conducted at various impact velocities as described later in this document.

The Contract Technical Manager was Mr. Charles Daye. The Contracting Officer was Ms. Linda Sink.

2.0 PURPOSE

The primary vehicles utilized in this test series were specially constructed Research Safety Vehicles (RSV) prepared by Minicars, Inc., of Goleta, California. The low speed impact tests were structured to evaluate the damageability of the vehicle design. One portion of the test series utilized a standard production vehicle (1980 Chevrolet Citation two-door) to obtain relative comparison data.

3.0 METHODOLOGY

A total of three vehicles were furnished by the government for this program:

<u>Quantity</u>	<u>Make and Model</u>	<u>Designation</u>
1	Minicars RSV	M5-10
1	Minicars RSV	M5-11
1	1980 Chevrolet Citation	2-Door

Each impact test was performed with one or two vehicles as defined in the test matrix, Table 3-1. The striking vehicle was designated as the bullet car, while the vehicle struck in the rear or side was designated as the target car. Impact speed in

TABLE 3-1. MINICARS RSV DAMAGEABILITY EVALUATION LOW SPEED IMPACTS 8342 TEST MATRIX

Test No.	Vehicles	Configuration	Impact Angle	Nominal Impact Speed	Actual Impact Speed
1	M5-10 into M5-11	Front-to-Rear	0°	12.5	12.9
2	M5-10 into M5-11	Front-to-Rear	0°	15	15.5
3	M5-10 into Citation	Front-to-Rear	0°	15	15.5
4	M5-10 into Citation	Front-to-Left Side	90°	5	5.2
5	M5-10 into M5-11	Front-to-Left Side	90°	5	5.1
6	M5-10 into Barrier	Head-On	0°	8	8.3
7	M5-10 into Barrier	Head-On	0°	17	17.5

Tests conducted August 27, 28, 29, 1980.

each case refers to the bullet car as the target car is stationary. All vehicles were re-used throughout the program with no repair or modification between subsequent tests.

The target car for front-to-rear impacts was centered longitudinally on the monorail track facing the barrier. For side impacts, the target car was placed perpendicular to the monorail track. In each case, the target car was stationary, with brakes released, and transmission in neutral.

The bullet car was towed to the specified test speed and released from the tow and guidance system immediately prior to impact with the target car. The service brakes of the bullet car were activated subsequent to impact with the target car. A delayed activation of the target car service brakes was effected at such time as the vehicle had rolled clear of the impact point.

All tests were conducted with both vehicle electrical systems disconnected. All windows were positioned closed and all movable body parts were closed and latched. Vehicles contained no instrumentation or surrogate occupants.

The front-to-rear impact point was defined as the point of coincidence of the longitudinal centerlines of the bullet and target cars. The front-to-side impact point was defined as the point of coincidence of the longitudinal centerline of the bullet car and the wheelbase centerline of the target car. Both vehicles were placed on the track such that the only contact during a test was with the other (impacting) vehicle.

Impact velocity was controlled within 0.5 mph of the nominal test speed. The bullet car was equipped with an on-board test abort system set to automatically activate if approach velocity exceeded the allowed margin in either direction.

4.0 DATA ACQUISITION

4.1 VEHICLE LOG

Documentation of vehicle pre-test preparation is contained in the Vehicle Preparation and Testing Log, included in this report as Appendix A. This log was maintained separately for each vehicle.

4.2 PHYSICAL MEASUREMENTS

Documentation of overall vehicle length, change in vehicle ride height, and maximum side impact deformation was accomplished through pre- and post-test measurements.

4.3 PHOTOGRAPHY REQUIREMENTS

The primary record of test performance and vehicle damage was provided by still and motion picture coverage. Up to six high-speed (400 frames-per-second), automatically activated cameras, along with two panning cameras (24 frames per second) were used to document each test.

Table 4-1 describes motion picture camera placement for the front-to-rear impacts. Table 4-2 describes camera placement for the front-to-side impacts, while Table 4-3 describes camera placement for the head-on barrier impacts.

An impact switch was attached to the forwardmost point on the bullet vehicle and connected to a strobe light, also attached to the bullet vehicle, to define the instant of impact for the benefit of all motion picture cameras.

Pre- and post-test still photographic coverage was provided for each test in accordance with the requirements detailed in Table 4-4.

TABLE 4-1. CAMERA LOCATIONS (FRONT-TO-REAR TESTS)


Test No: 1, 2, 3 Test Date: 8-27-80

Test Type: Front-to-Rear Tests

Vehicle A (bullet) RSV M5-10

Vehicle B (target) RSV M5-11, Chevrolet Citation

Comments: _____



CAMERA	YES
STILLS	X
SLIDES	X
MOVIE	X
POLAROID	
VIDEO	

CAMERA SYMBOLS


- PIT
- GROUND
- BARRIER
- OVERHEAD
- ON-BOARD

FRAME RATE

1. 1000 fr/sec
2. 200 fr/sec
3. Other 24 fr/sec
4. 400 fr/sec
5. 500 fr/sec
6. 128 fr/sec

TIMING LIGHT SPEED

1. 100 Hz (10 msec/light)
2. 200 Hz (5 msec/light)
3. Other _____



Loc. No.	Location	Field of View	Lens Size	Frm Rate	Tmng Spd	Ser No	Impact Dist-X	C.L. Dist-Y	CAM Hght-Z
A	South Side	Documentation (B staying on B)	12.5-75	3	n/a	30947	48"	54'	58"
B	South Side	Documentation (B going to T)	12.5-75	3	n/a	31488	106"	52'	62"
C	Catwalk	O/A elevated view (both vehicles at impact)	12	6	n/a	900	105"	58'	19'8"
D	South Side	view on bumper interaction	25	4	n/a	901	23"	54'	51"
E	South Side	Oblique uptrack - interaction to rest	16	4	n/a	6495	19'	45'	64"
F	South Side	Oblique downtrack - interaction to rest	25	4	n/a	902	-27"	59'	59"
G	South Side	view panning close-up on bumper interaction	50	4	n/a	6548	6"	51'	36"
H	North Side	Opposite side view - bumper interaction	25	4	n/a	6549	30"	-54'	61"

TABLE 4-2. CAMERA LOCATIONS (FRONT-TO-SIDE TESTS)


Test No: 4, 5 Test Date: 8-28-80

Test Type: Front-to-Side

Vehicle A (bullet) RSV M5-10

Vehicle B (target) RSV M5-11, Chevrolet Citation

Comments: _____



- CAMERA SYMBOLS**
- PIT
 - GROUND
 - BARRIER
 - OVERHEAD
 - ON-BOARD
- FRAME RATE**
1. 1000 fr/sec
 2. 200 fr/sec
 3. Other 24 fr/sec
 4. 400 fr/sec
 5. 500 fr/sec
 6. 128 fr/sec
- TIMING LIGHT SPEED**
1. 100 Hz (10 msec/light)
 2. 200 Hz (5 msec/light)
 3. Other _____

CAMERA	YES
STILLS	X
SLIDES	X
MOVIE	X
POLAROID	
VIDEO	

LOC. NO.	Location	Field of View	Lens Size	Frm Rate	Tmng Spd	Ser No	Impact Dist-X	C.L. Dist-Y	CAI: Hght-Z
A	South Side	Documentation (tracking)	12.5-75	3	n/a	31488	-76"	50'4"	60"
B	Catwalk	O/A elevated ⊥ view (both vehicles at impact)	18	6	n/a	900	0	57'	19'8"
C	Catwalk	Elevated ⊥ close-up, front end at impact	50	6	n/a	6548	-30"	57'4"	19'10"
D	South Side	⊥ view, front end at impact (medium shot)	25	6	n/a	901	-29"	51'	52"
E	South Side	⊥ view, front end at impact (extreme close-up)	50	2	n/a	902	-30"	49'3"	28"
F	North Side	Opposite side ⊥ view, front end at impact (med)	25	6	n/a	6549	-19"	-30'	30"

TABLE 4-3. CAMERA LOCATIONS (BARRIER TESTS)

Test No: 6, 7 Test Date: 8-29-80

Test Type: Head-On Barrier Impact

Vehicle A (bullet) RSV M5-10

Vehicle B (target)

Comments:

CAMERA	YES
STILLS	X
SLIDES	X
MOVIE	X
POLAROID	
VIDEO	

CAMERA SYMBOLS



- PIT
- GROUND
- BARRIER
- OVERHEAD
- ON-BOARD

FRAME RATE

1. 1000 fr/sec
2. 200 fr/sec
3. Other 24 fr/sec
4. 400 fr/sec
5. 500 fr/sec
6. 128 fr/sec

TIMING LIGHT SPEED

1. 100 Hz (10 msec/light)
2. 200 Hz (5 msec/light)
3. Other



Loc. No.	Location	Field of View	Lens Size	Frm Rate	Tmng Spd	Ser No	Impact Dist-X	C.L. Dist-Y	CAM Hght-Z
A	South Side	Documentation (tracking)	12.5-75	3	n/a	31488	-48"	36'	62"
B	South Side	O/A ⊥ view, full vehicle at impact	16	6	n/a	6495	0	33'9"	58"
C	South Side	Medium ⊥ view, 2/3 vehicle at impact	25	4	n/a	6548	0	31'6"	43"
D	South Side	ECU ⊥, bumper face at impact	50	4	n/a	902	-6"	30'9"	36"
E	Catwalk	CU ⊥, elevated, bumper and nose at impact	50	4	n/a	900	-16"	43'9"	19"
F	North Side	Medium ⊥ view, 1/2 vehicle at impact, opp. side	25	4	n/a	6549	0	-24'	38"
G	Overhead	Front_half_of_vehicle	16	4	n/a	901	-18"	0	23'

TABLE 4-4. STILL PHOTOGRAPHIC REQUIREMENTS

1. Left and right side view of each impacting vehicle.
 2. Closeup views of bumper contact, left and right sides.
 3. Front view of bullet vehicle.
 - Three-quarter left view.
 - Three-quarter right view.
 4. Rear (or side) view of target vehicle.
 - Three-quarter left view.
 - Three-quarter right view.
-

Requirements pertain to color photos as well as 35 mm color slides.

Two release prints containing motion picture film coverage of each test, along with a complete set of color photos and 35 mm color slides from each test, have been forwarded to the sponsor in advance of this report.

4.4 VEHICLE DAMAGE APPRAISALS

Three independent damage appraisals were obtained for the Chevrolet Citation following tests no. 3 and 4. Each appraisal contains an analysis of the damage sustained and an estimate of parts and labor costs required to return the vehicle to original pre-test condition. A copy of each of these appraisals, along with a comprehensive summary sheet, is presented in Appendix B.

5.0 TEST RESULTS

A discussion of the configuration and test results from each of the seven impacts is included in this section of the report. Pre- and post-test photographs further describing each test are included in Appendix C.

5.1 TEST NO. 1: M5-10 FRONT-INTO-M5-11 REAR (12.5 MPH)

Figure C-1 presents an overall view of the test configuration while Figure C-2 presents a close-up view of the bumper match. Nominal impact speed was 12.5 mph, with actual test speed 12.9 mph.

5.1.1 Post-test Dimensional Measurements

M5-10 Overall length = 177.5 inches (no change from pre-test)

M5-11 Overall length = 177.5 inches (no change from pre-test)

Attitude: M5-10 LF 30.8" RF 30.3" (no change from pre-test)

LR 31.1" RR 30.7"

M5-11 LF 30.5" RF 30.7" (no change from pre-test)

LR 31.2" RR 31.3"

5.1.2 Post-test Observations

5.1.2.1 M5-10 Vehicle

The M5-10 bullet vehicle suffered no visible damage.

5.1.2.2 M5-11 Vehicle

Damage to the M5-11 target vehicle was minor and apparently cosmetic only. One small crack appeared at the lower left corner of the taillight panel, adjacent to the rear fender seam. During vehicle construction, this area was finished for painting by covering with a layer of body putty. The crack observed appeared to be in the body putty only (see Figure C-3).

A second small crack appeared in the seam where the lateral panel below the rear hatch window mates with the right rear fender panel. As with the previously noted crack, this appeared to extend into the body putty (seam filler) only (see Figure C-4).

A minor wrinkle appeared in the face of the rear bumper covering that was not significant enough to stand out in photographs.

Both the left and right hand passenger doors and the rear hatch door functioned normally post-test.

5.2 TEST NO. 2: M5-10 FRONT-INTO-M5-11 REAR (15.0 MPH)

The configuration for this test was similar to that for Test No. 1, shown in Figures C-1 and C-2. Nominal impact speed was 15.0 mph, with actual test speed 15.5 mph.

5.2.1 Post-test Dimensional Measurements

M5-10 Overall length = 177.5 inches (no change from pre-test)

M5-11 Overall length = 177.0 inches (shortened 0.5 inches)

Attitude:	M5-10	LF	<u>30.8"</u>	RF	<u>30.3"</u>	(no change from pre-test)
		LR	<u>31.2"</u>	RR	<u>30.7"</u>	
	M5-11	LF	<u>30.6"</u>	RF	<u>30.7"</u>	(no change from pre-test)
		LR	<u>31.2"</u>	RR	<u>31.5"</u>	

5.2.2 Post-test Observations

5.2.2.1 M5-10 Vehicle

The M5-10 bullet vehicle suffered no visible damage.

5.2.2.2 M5-11 Vehicle

The crack noted in the lower left corner of the M5-11 tail-light panel, resulting from Test No. 1, propagated vertically an additional 1/2-3/4 inch, to a total of approximately 4.0 inches.

The bond line at the upper forward edge of the lateral panel below the rear hatch window failed, allowing the panel to translate upward approximately 1.5 inches (see Figure C-5). This action also caused a crack to appear in the fender seams adjoining this same panel, as shown in Figure C-6.

The rear bumper assumed a permanent bow as shown in Figure C-7. A slight bow was observed on the M5-11 vehicle upon delivery. This condition was exaggerated somewhat by testing.

The left rear inside fender panel-to-fender bond failed, allowing the panel to fall forward as shown in Figure C-8.

A wrinkle appeared in the horizontal upper surface of the rear bumper covering material, on both sides of the M5-11 vehicle, near the rear fender corners. This may be seen in the overall rear view of the vehicle presented in Figure C-9.

The above conditions appear to indicate that some level of permanent damage was sustained by the structure behind the soft bumper face material.

5.3 TEST NO. 3: M5-10 FRONT-INTO-CHEVROLET CITATION REAR (15.0 MPH)

Figure C-10 presents an overall view of the test configuration while Figure C-11 shows a close-up view of the bumper match. Nominal impact speed was 15.0 mph, with actual test speed 15.5 mph.

5.3.1 Post-test Dimensional Measurements

M5-10 Overall length = 177.5 inches (no change from pre-test)
Citation Overall length = 176.5 inches (shortened 1.5 inches)

Attitude: M5-10 LF 30.6" RF 30.3" (no change from pre-test)
LR 31.1" RR 30.6"

Citation LF 29.3" RF 29.3" (Rear end lowered
LR 28.0" RR 28.4" 1.0" from pre-test)

5.3.2 Post-test Observations

5.3.2.1 M5-10 Vehicle

The M5-10 bullet vehicle suffered no apparent damage.

5.3.2.2 Chevrolet Citation

Post-test examination of the Chevrolet Citation revealed significant pressure buckles forward of and above each rear wheel opening as shown in Figure C-12.

Both the left and right side taillight lenses cracked as shown in Figure C-13.

The bumper face bar showed no significant damage. The energy absorbers behind the bumper face bar stroked approximately 1.0 inch and returned to the pre-test condition.

A small pressure buckle occurred near the upper rear corner of the fuel fill door and at a corresponding point on the opposite side of the vehicle (see Figure C-14). This photograph also shows the general downward movement of the rear of the vehicle when compared to the pre-test condition.

Further examination of the Chevrolet Citation revealed definite damage to the rear body floor panel and unibody structure. Both the left and right side passenger doors and windows and the rear hatch door functioned normally post-test.

5.4 TEST NO. 4: M5-10 FRONT-INTO-CHEVROLET CITATION LEFT SIDE
(5.0 MPH)

Figures C-15 and C-16 present the test configuration. Nominal impact speed was 5.0 mph, with actual test speed 5.2 mph.

5.4.1 Post-test Dimensional Measurements

M5-10 Overall length = 177.5 inches (no change from pre-test)

Citation Overall length = 176.5 inches (no change from pre-test)

Attitude: M5-10 LF 30.8" RF 30.4" (no change from pre-test)
LR 31.4" RR 30.4"

Citation LF 29.5" RF 29.3" (no change from pre-test)
LR 28.0" RR 28.5"

5.4.2 Post-test Observations

5.4.2.1 M5-10 Vehicle

The M5-10 bullet vehicle suffered no visible damage.

5.4.2.2 Chevrolet Citation

Obvious damage to the Chevrolet Citation was confined to the driver's door skin and lock pillar assembly. Maximum depression depth on the door skin was approximately 1.5 inches. The door opened and closed normally post-test, and the window remained intact and operational.

Probable damage occurred to the door frame and reinforcing beam behind the outer skin. Figures C-17 and C-18 present the post-test views of the vehicle.

5.5 TEST NO. 5: M5-10 FRONT-INTO-M5-11 LEFT SIDE (5.0 MPH)

The configuration for this test is presented in Figures C-19 and C-20. Nominal impact speed was 5.0 mph, with actual test speed 5.1 mph.

5.5.1 Post-test Dimensional Measurements

M5-10 Overall length = 177.5 inches (no change from pre-test)

M5-11 Overall length = 177.0 inches (no change from pre-test)

Attitude: M5-10 LF 30.7" RF 30.5" (no change from pre-test)

LR 31.1" RR 30.2"

M5-11 LF 31.3" RF 31.5" (Front end raised 0.75
LR 31.2" RR 31.4" inches from pre-test)

5.5.2 Post-test Observations

5.5.2.1 M5-10 Vehicle

The M5-10 bullet vehicle suffered no visible damage.

5.5.2.2 M5-11 Vehicle

Two small impressions were left on the outer skin of the M5-11 target vehicle door, corresponding to the hard spots on the front of the bullet vehicle (projections tangent to insides of head lights). Width of these impressions was approximately 6.0 inches in each case, with a 4.5-inch vertical line evident in the rear impression that was not evident in the front impression. Post-test operation of the gullwing door was normal, with no damage apparent to any of the window surfaces. It was not determined whether any damage occurred to the reinforcing member behind the outer door skin.

Post-test views of the vehicle, showing the damage noted on the previous page, are included as Figures C-21 and C-22.

5.6 TEST NO. 6: M5-10 FRONT-INTO-FIXED BARRIER (8.0 MPH)

The test configuration is shown in Figure C-23. Nominal impact speed was 8.0 mph, with actual test speed 8.3 mph.

5.6.1 Post-test Dimensional Measurements

M5-10 Overall length = 177.5 inches (no change from pre-test)

Attitude: M5-10 LF 30.7" RF 30.3" (no change from pre-test)
LR 31.0" RR 30.3"

5.6.2 Post-test Observations (M5-10 Vehicle)

The left and right side turn signal lamp frames were anchored to an aluminum base plate by four 1/4-inch bolts on each side. These bolts were threaded into nutsert fasteners installed in the base plate. During Test No. 6, the front pair of bolts on each lamp pulled the nutsert fasteners through the base plate material. Figure C-24 presents a post-test view of the right side lamp.

No other damage to the M5-10 vehicle was apparent as a result of this test.

5.7 TEST NO. 7: M5-10 FRONT-INTO-FIXED BARRIER (17.0 MPH)

The configuration for this test was similar to that for Test No. 6, shown in Figure C-23. Nominal impact speed was 17.0 mph, with actual test speed 17.5 mph.

5.7.1 Post-test Dimensional Measurements

M5-10 Overall length = 174.0 inches (shortened 3.5 inches
from pre-test)

Attitude: M5-10 LF 30.5" RF 30.2" (no change from pre-test)
LR 31.0" RR 30.4"

5.7.2 Post-test Observations (M5-10 Vehicle)

Both headlight units broke loose from their lower retainers. The left and right side turn signal lamps, along with their base plate, were forced rearward, resulting in residual translation of approximately 6.0 inches. Noticeable permanent deformation occurred across the entire lateral bumper face with some structural damage occurring across the entire front surface behind the bumper face. The vehicle was observed leaking coolant fluid due to a broken feed line and/or torn radiator hose.

Post-test operation of both gullwing doors was normal. No cracks were observed in the windshield or in any of the other window surfaces. Post-test operation of the front luggage compartment lid and the rear hatch door were normal.

Figures C-25 through C-29 present various views of the post-test condition of the M5-10 vehicle.

APPENDIX A
VEHICLE PREPARATION AND TESTING LOG

APPENDIX A - VEHICLE PREPARATION AND TESTING LOG

PROJECT Damageability Tests of Minicars RSV VEHICLE IDENTIFICATION: _____

TASK Low Speed Impacts Year N/A Make Minicars RSV Model M5-10

SUBTASK NUMBER	SUBTASK DESCRIPTION	DONE BY	DATE	SPECIAL INSTRUCTIONS/COMMENTS
1	Inspect vehicle for defects such as loose structural or suspension components.	R.G.	8-27	Note nature of damage and corrective action in Vehicle Log. (Re-adjust left door)
2	Determine unloaded vehicle weight by wheel. Full liquid capacities, no cargo or occupants.	J.S. V.T.	8-27	LF 546 lb RF 588 lb LR <u>761 lb</u> RR <u>707 lb</u> 2602 lb
3	Wash vehicle if necessary.	J.S.	8-27	
4	Inflate tires to manufacturer's recommended pressure.	V.T.	8-27	Front 30 psi Rear <u>35 psi</u>
5	Secure spare tire, jack, tools, etc., per manufacturer's specifications.	R.G.	8-27	
6	Scribe a level line on each side of the vehicle near each wheel. Record height at each position.	R.G.	8-27	LF <u>30.5"</u> RF <u>30.5"</u> LR <u>30.5"</u> RR <u>30.5"</u>
7	Determine overall length of vehicle.	R.G.	8-27	<u>177.5"</u> (at vehicle centerline)
8	Install tow and guide plates to forward understructure in approved manner.	V.T.	8-27	Bullet vehicle only. (M5-10)

APPENDIX A - VEHICLE PREPARATION AND TESTING LOG

PROJECT Damageability Tests of Minicars RSV VEHICLE IDENTIFICATION:

Year N/A Make Minicars RSV Model M5-10

TASK Low Speed Impacts

SUBTASK NUMBER SUBTASK DESCRIPTION DONE BY DATE SPECIAL INSTRUCTIONS/COMMENTS

9 Verify fuel tank is filled and other liquids are at the proper levels.

V.T. 8-27 Gasoline drained and replaced with stoddard solvent.

10 Deliver vehicle to the Crash Test Facility

APPENDIX A - VEHICLE PREPARATION AND TESTING LOG

PROJECT	Damageability Tests of Minicars RSV	VEHICLE IDENTIFICATION:		
		Year	Make	Model
TASK	Low Speed Impacts	N/A	Minicars RSV	M5-11
SUBTASK NUMBER	SUBTASK DESCRIPTION	DONE BY DATE SPECIAL INSTRUCTIONS/COMMENTS		
1	Inspect vehicle for defects such as loose structural or suspension components.	R.G.	8-27	Note nature of damage and corrective action in Vehicle Log. (none)
2	Determine unloaded vehicle weight by wheel. Full liquid capacities, no cargo or occupants.	J.S. V.T.	8-27	LF <u>540 lb</u> RF <u>565 lb</u> LR <u>729 lb</u> RR <u>700 lb</u> 2544 lb
3	Wash vehicle if necessary.	J.S.	8-27	
4	Inflate tires to manufacturer's recommended pressure.	V.T.	8-27	Front <u>30</u> psi Rear <u>35</u> psi
5	Secure spare tire, jack, tools etc., per manufacturer's specifications.	R.G.	8-27	
6	Scribe a level line on each side of the vehicle near each wheel. Record height at each position.	R.G.	8-27	LF <u>30.5"</u> RF <u>30.5"</u> LR <u>30.5"</u> RR <u>30.5"</u>
7	Determine overall length of vehicle.	R.G.	8-27	<u>177.5"</u> (at vehicle centerline)
8	Install tow and guide plates to forward understructure in approved manner.	N/A		Bullet vehicle only. (M5-10)

APPENDIX A - VEHICLE PREPARATION AND TESTING LOG

PROJECT	Damageability Tests of Minicars RSV	VEHICLE IDENTIFICATION:		
TASK	Low Speed Impacts	Year	Make	Model
		N/A	Minicars RSV	M5-11
SUBTASK NUMBER	SUBTASK DESCRIPTION	DONE BY DATE SPECIAL INSTRUCTIONS/COMMENTS		
9	Verify fuel tank is filled and other liquids are at the proper levels.	V.T.	8-27	Gasoline drained and replaced with stoddard solvent.
10	Deliver vehicle to the Crash Test Facility			

APPENDIX A - VEHICLE PREPARATION AND TESTING LOG

PROJECT	Damageability Tests of Minicars RSV	VEHICLE IDENTIFICATION:		
TASK	Low Speed Impacts	Year	Make	Model
		1980	Chevrolet	Citation Two-Door
SUBTASK NUMBER	SUBTASK DESCRIPTION	DONE BY	DATE	SPECIAL INSTRUCTIONS/COMMENTS
1	Inspect vehicle for defects such as loose structural or suspension components.	R.G.	8-28	Note nature of damage and corrective action in Vehicle Log. (none)
2	Determine unloaded vehicle weight by wheel. Full liquid capacities, no cargo or occupants.	J.S. V.T.	8-27	LF 896 lb RF 884 lb LR <u>484 lb</u> RR <u>460 lb</u> 2724 lb
3	Wash vehicle if necessary.	J.S.	8-28	
4	Inflate tires to manufacturer's recommended pressure.	V.T.	8-27	Front 26 psi Rear 26 psi
5	Secure spare tire, jack, tools, etc., per manufacturer's specifications.	R.G.	8-28	
6	Scribe a level line on each side of the vehicle near each wheel. Record height at each position.	R.G.	8-28	LF 29.3" RF 29.3" LR 28.8" RR 29.5"
7	Determine overall length of vehicle.	R.G.	8-28	178" (at vehicle centerline)
8	Install tow and guide plates to forward understructure in approved manner.	N/A		Bullet vehicle only. (M5-10)

APPENDIX A - VEHICLE PREPARATION AND TESTING LOG

PROJECT Damageability Tests of Minicars RSV

VEHICLE IDENTIFICATION:

TASK	Year	Make	Model
Low Speed Impacts	1980	Chevrolet	Citation Two-Door

SUBTASK NUMBER	SUBTASK DESCRIPTION	DONE BY	DATE	SPECIAL INSTRUCTIONS/COMMENTS
9	Verify fuel tank is filled and other liquids are at the proper levels.	V.T.	8-27	
10	Deliver vehicle to the Crash Test Facility			

APPENDIX B
CHEVROLET CITATION DAMAGE APPRAISALS

TABLE B-1. APPRAISAL SUMMARY FOR REAR IMPACT AT 15.5 MPH

	<u>Helpn-U Appraisals</u>	<u>Western Appraisers</u>	<u>Ed Johnson Auto Appraisers</u>	<u>Average</u>
Labor	\$436.50	\$483.00	\$325.50	\$415.00
Parts	78.00	94.70	107.00	93.23
Sublet	47.80	166.00	33.00	82.27
Tax	<u>6.29</u>	<u>13.04</u>	<u>7.00</u>	<u>8.78</u>
Total	\$568.59	\$756.74	\$472.50	\$599.28

TABLE B-2. APPRAISAL SUMMARY FOR SIDE IMPACT AT 5.2 MPH

	<u>Helpn-U Appraisals</u>	<u>Western Appraisers</u>	<u>Ed Johnson Auto Appraisers</u>	<u>Average</u>
Labor	\$223.50	\$261.10	\$310.50	\$265.03
Parts	-	76.25	79.00	51.75
Sublet	24.50	34.30	33.00	30.60
Tax	<u>1.23</u>	<u>5.53</u>	<u>5.60</u>	<u>4.12</u>
Total	\$249.23	\$377.18	\$428.10	\$351.50

It should be noted that, on the original appraisal sheets, parts discounts from 0-15% were included. The figures shown above have been adjusted to 0% parts discount, in each case, to permit direct comparison.

RCA No. 10010112

CLIENT _____

Page No. 1 of 1

ATTN: ALL K... Your No. 10 #04968

INSURED

Name: LYNN INC
 Address: 1301 W. LINNACLE PEAK RD.
 Address (Cont.): PHOENIX, AZ 85027
 Phone (Home & Business): 942-3300

CLAIMANT

Name: _____
 Address: _____
 Address (Cont.): N/H
 Phone (Home & Business): _____

Vehicle Make, Year and Body Type: 480 Chev Citation License No.: NONE Serial/Identification No.: X1X0B7A 632639 Mileage: 00037.0

Exterior: <u>NEW</u>	Interior: <u>NEW</u>	Color: <u>RED</u>	Approx. Retail: <u>\$ 6,500.00</u>	Approx. Salvage: <u>\$ N/A</u>
Date of Loss: <u>N/A</u>	Assignment Received: <u>9/9/0</u>	Contacted Owner: <u>9/9/0</u>	Inspected Vehicle: <u>9/11/0</u>	Date of A/Price: <u>9/12/0</u>
			Date Closed: <u>9/12/0</u>	

Labor: 29.1 Hours @ 15.00 \$ 436.50

Labor: _____ Hours @ _____ \$ _____

Parts: 78.00 Less % 15% \$ 66.30

Parts: _____ Less % _____ \$ _____

Sublet and Net Items: _____ \$ 47.80

Tax @ 5 % On \$ 114.10 \$ 5.71

Advance Charges: _____ \$ _____

REPAIR TOTAL _____ \$ 556.31*

Deductible (-) _____ \$ N/A

Betterment (-) _____ \$ N/A

Appearance Allowance (+) _____ \$ N/A

RECOMMENDATION _____ \$ 556.31

The undersigned agrees to complete and guarantee the repairs listed on the attached sheet(s) at a total price of \$556.31 including all towing and storage charges incidental thereto.

Repairer: Courtesy Chevrolet
 Address: 1233 E Camelback Rd.
 City/State: Phoenix, AZ 85014 Phone: 279-3230
 By: X Kellie
 Down Time (Approx.): N/A

OWNER MUST AUTHORIZE

COMMENTS

EXCLUDE 4/DOOR & 4/PILLAR DAMAGE!

*Adjusted to \$568.59 to delete parts discount.

Signature of Appraiser: [Signature] No. 0055079 Kind of Loss: Coll.

THIS IS NOT AN AUTHORIZATION TO MAKE REPAIRS

Repair	Details of Repairs and or Replacements	Est. Labor	Flat Rate	Ret. Labor	Parts and Materials	Sublet and Net Items
X	REAR BODY K... (partially obscured)		0.9	-	-	-
X	STRAIGHTENING TIME	1.5	-	-	-	-
X	REAR TAILAMP LENS - (Right) T-Type	-	0.4	-	39.00	-
X	" " (Left) "	-	0.4	-	39.00	-
X	REAR BODY PANEL Below Lift Gate	3.0	-	1.0	-	-
X	REAR FRAME X-MBR & SIDE RAILS & FLOOR	3.0	-	1.0	-	-
X	R/QT PANEL ASSY (incl. REINFORC. AS NEED)	6.5	-	2.2	-	-
X	L/QT " " " " " " " " } SEE NOTE	4.0	-	1.8	-	-
	PAINT MATERIALS (5.4 Hrs @ 7.00 Hr)	-	-	-	-	47.80

NOTE: L/QT PANEL METAL FINISH & PAINT LABOR TIME EXCLUDES DAMAGE AT LEFT LOCK PILLAR!

AUTHORIZATION TO REPAIR MUST COME FROM OWNER

TOTALS 22.9 / 1.7 / 5.4 / 78.00 / 47.80



VEHICLE DAMAGE APPRAISAL SHEET

RCA No 9009-270

Phone 602 247-0903

CLIENT [Handwritten Name]

Page No 1 of 2

ATTN [Handwritten Name] Your No: [Handwritten Number]

INSURED	Name DYNAMIC SCIENCE TRNG	CLAIMANT	Name
	Address 1850 W. PINNACLE PEAK RD		Address N/A
	Address (Cont.) Phoenix, AZ 85027		Address (Cont.)
	Phone (Home & Business) 946-3300		Phone (Home & Business)

Vehicle Make, Year and Body Type: 198 Chev Citation License No: NONE Serial/Identification No: X1X087A632639 Mileage: 00037.0

Tires: NEW	Exterior: NEW	Interior: NEW	Color: RED	Approx. Retail: \$6,500.00	Approx. Salvage: \$ N/A
Date of Loss: N/A	Assignment Received: 9/9/10	Contacted Owner: 9/9/10	Inspected Vehicle: 9/11/10	Date of A/Price: 9/15/10	Date Closed: 9/15/10

The undersigned agrees to complete and guarantee the repairs listed on the attached sheet(s) at a total price of \$ 249.23 including all towing and storage charges incidental thereto.

Repairer: Ric's Body & Paint
Address: 9545 N. CAVE CREEK RD
City/State: Phoenix, AZ Phone: 997-7506
By: Ric

Down Time (Approx.): N/A

Labor: 14.9 Hours @ 15.00	\$ 223.50
Labor: - Hours @ -	\$ -
Parts: - Less % -	\$ -
Parts: - Less % -	\$ -
Sublet and Net Items	\$ 24.50
Tax @ 5 % On \$ 24.50	\$ 1.23
Advance Charges	\$ -
REPAIR TOTAL	\$ 249.23
Deductible (-)	\$ N/A
Betterment (-)	\$ N/A
Appearance Allowance (+)	\$ N/A
RECOMMENDATION	\$ 249.23

OWNER MUST AUTHORIZE

COMMENTS

SIDE Impact ONLY: EXCLUDE Impact DAMAGE (Displaced Metal) Resulting from REAR Collision!

Signature of Appraiser: [Handwritten Signature] No: 0055079 Kind of Loss: Coll.



WESTERN APPRAISERS OF ARIZONA

TELEPHONE (602) 266-5626
P. O. BOX 7611
PHOENIX, ARIZONA 85011

Page 1
Remission

Date Sept 3, 1980

Co. Claim No. _____

Final Billing c/o WESTERN APPRAISERS Office Phoenix Appraiser T. O. Donnell P-127-06
OUR FILE NUMBER

Assured Dynalene Science Claimant _____

MAKE	YEAR	MODEL	BODY STYLE	MOTOR NUMBER	LICENSE NO.	MILEAGE
<u>Chevrolet</u>	<u>80</u>	<u>Citation</u>	<u>2DR.</u>	<u>1X0E7A6325634</u>	<u>None</u>	<u>37</u>

REPAIR	REPLACE	DETAILS OF REPAIR AND REPLACEMENTS	FLAT RATE IN HOURS	ALLOWED LABOR IN HRS.	PARTS OR MATERIAL	SUBLET
	X	<u>Rear bumper R/C</u>		<u>1.5</u>		<u>107.00</u>
X		<u>Energy absorbers R/L & L/S</u>		<u>0.5</u>		
X		<u>Rear body panel</u>		<u>1.5</u>		
	X	<u>1/2 Tail lamp</u>		<u>0.2</u>	<u>26.50</u>	
	X	<u>1/2 Tail lamp</u>		<u>0.2</u>	<u>26.50</u>	
X		<u>Deck lid (Hatchback) align</u>		<u>0.4</u>		
	X	<u>R/C Bumper filler and</u>		<u>0.2</u>	<u>20.85</u>	
	X	<u>1/2 Bumper filler and</u>		<u>0.2</u>	<u>20.85</u>	
X		<u>R/R 1/4 Panel</u>		<u>8.5</u>		
X		<u>1/2 1/4 Panel</u>		<u>3.5</u>		
X		<u>Working R/L Rad, Wild Bolt</u>		<u>8.5</u>		
		<u>Pin Straps (Tape & A) Pat</u>		<u>1.5</u>		<u>10.50</u>
		<u>Refinish</u>		<u>5.5</u>		<u>38.50</u>
		<u>Materials</u>				<u>10.00</u>
*Adjusted to \$756.74 to delete parts discount.						
THIS IS NOT A REPAIR AUTHORIZATION Authorization must be obtained from owner of vehicle.				<u>32.2</u>	<u>94.70</u>	<u>166.00</u>

THIS DOES NOT VERIFY COVERAGE, NOR AN AGREEMENT TO PAY FOR REPAIR

For \$ 746.27 less Ded. \$ 0 the undersigned agrees to complete and guarantee all loss repairs to the above vehicle.

NO SUPPLEMENTS WITHOUT PRIOR APPROVAL

FIRM _____

ADDRESS _____

BY _____ B-7

Form WA-101

Labor 32.2 @ 15.00 \$ 483.00
 Parts 4 10.90 \$ 85.23
 Net Parts \$ 85.23
 Tax 251.23 x 5% \$ 12.56
 Sublet \$ 166.00
 Adv. Charges \$ 746.27
 GRAND TOTAL \$ 746.27*



WESTERN APPRAISERS
OF ARIZONA

TELEPHONE (602) 266-5626
P. O. BOX 7611
PHOENIX, ARIZONA 85011

Page II
45 Collision

Date Sept 3, 1980

Co. Claim No. _____

Final Billing c/o WESTERN APPRAISERS Office Phoenix Appraiser T.O. Dinell P-127-06
OUR FILE NUMBER

Assured Dynamic Science Claimant _____

MAKE	YEAR	MODEL	BODY STYLE	MOTOR NUMBER	LICENSE NO.	MILEAGE
<u>Chevrolet</u>	<u>80</u>	<u>Citation</u>	<u>2DR</u>	<u>1X087A6325639</u>	<u>None</u>	<u>37</u>

REPAIR	REPLACE	DETAILS OF REPAIR AND REPLACEMENTS	FLAT RATE IN HOURS	ALLOWED LABOR IN HRS.	PARTS OR MATERIAL	SUBLET
	X	<u>1/5 Door outer panel.</u>		<u>5.0</u>	<u>76</u>	<u>25</u>
	X	<u>Door frame.</u>		<u>1.0</u>		
	X	<u>4R 1/4 panel (RT section)</u>		<u>5.0</u>		
		<u>hook pillar (weld)</u>		<u>1.5</u>		
		<u>Retinish</u>		<u>4.9</u>		<u>34.30</u>
*Adjusted to \$377.18 to delete parts discount.						
THIS IS NOT A REPAIR AUTHORIZATION Authorization must be obtained from owner of vehicle.				<u>17.4</u>	<u>76</u>	<u>25</u>
						<u>34.30</u>

THIS DOES NOT VERIFY COVERAGE, NOR AN AGREEMENT TO PAY FOR REPAIR

For \$ 369.07 less Ded. \$ 0 the undersigned agrees to complete and guarantee all loss repairs to the above vehicle.

NO SUPPLEMENTS WITHOUT PRIOR APPROVAL

FIRM _____

ADDRESS _____

BY _____ B-8

Form WA-101

Labor 17.4 @ \$15.00 \$ 261.10
 Parts 4/10%
 Net Parts \$ 68.62
 Tax 62.92 x 5% \$ 5.15
 Sublet \$ 34.30
 Adv. Charges \$ 369.07
 GRAND TOTAL \$ 369.07*

Form of Policy Number

ED JOHNSON AUTO APPRAISERS

Date

7214 NORTH 36th DRIVE

PHOENIX, ARIZONA 85021

841-7710
PHONE 939-8826

Assured Claimant

Place Inspected Phoenix, Arizona

Remarks As per Ed Johnson

Appraiser Ed Johnson

CAR MAKE, YEAR AND BODY TYPE Snow 80. Station Wagon MILEAGE 00037 LICENSE NO. --- MTR/SER. NO. AUS 7A1325639

REPAIR	REPLACE	DETAILS OF REPAIRS AND/OR REPLACEMENTS	LABOR HOURS	PARTS AND MATERIAL (LIST PRICE)	SUBLET AND RET ITEMS
✓		Bumper rear energy absorber (R+L bumper)	0.9	33.15	
✓		7 Lamp lens L/R	0.3	26.50	
✓		" " " " " "	0.3	26.50	
✓		Bumper killer and X	0.2	20.85	
✓		Fender + Pin body	6.0	-	
✓		Oil pan	2.0	-	
✓		" " " "	2.0	-	
✓		Washers	4.0	-	28.00
✓		TRK-stripe (tape)	1.0	-	5.00

The undersigned agrees to complete and guarantee all repairs as listed for \$ 472.50 including all towing & storage charges incidental thereto.

By _____ Repair

Insurance Co. _____

Betterment Charges \$ 0

Insurance Deductible \$ 0

To Be Deducted from Total \$ 0

Labor 21.7 Hrs. @ \$ 15.00 \$ 325.50

Parts Cost \$107.00

Less Discount 0% \$ 0

Net Parts Cost \$107.00

Sublet \$33.00

Other Charges \$-

Tax 5% () \$ 7.00

Total \$ 472.50

Less Deduction \$ 0

GRAND TOTAL \$ 472.50

THIS IS NOT AN AUTHORIZATION TO REPAIR B-9

INSURANCE COPY

APPENDIX C
TEST SERIES PHOTOGRAPHS




FIGURE C-1. PRE-TEST NO. 1, VEHICLE CONFIGURATION.




FIGURE C-2. PRE-TEST NO. 1, VEHICLE CONFIGURATION.




FIGURE C-3. POST-TEST NO. 1, CRACK IN TAILLIGHT PANEL OF M5-11 TARGET VEHICLE.




FIGURE C-4. POST-TEST NO. 1, CRACK IN REAR FENDER PANEL SEAM OF M5-11 TARGET VEHICLE.




FIGURE C-5. POST-TEST NO. 2, BOND LINE FAILURE BELOW REAR HATCH DOOR OF M5-11 TARGET VEHICLE.






FIGURE C-6. POST-TEST NO. 2, CRACK IN REAR FENDER PANEL SEAM OF M5-11 TARGET VEHICLE.




006746

FIGURE C-7. POST-TEST NO. 2, REAR BUMPER OF M5-11 TARGET VEHICLE.



006739

FIGURE C-8. POST-TEST NO. 2, INSIDE LEFT REAR FENDER PANEL OF M5-11 TARGET VEHICLE.



006161

FIGURE C-9. POST-TEST NO. 2, OVERALL REAR VIEW OF M5-11 TARGET VEHICLE.

006111




FIGURE C-10. PRE-TEST NO. 3, VEHICLE CONFIGURATION.

006113




FIGURE C-11. PRE-TEST NO. 3, VEHICLE CONFIGURATION.




FIGURE C-12. POST-TEST NO. 3, REAR QUARTER PANEL OF CHEVROLET CITATION TARGET VEHICLE.



FIGURE C-13. POST-TEST NO. 3, REAR TAILLIGHT LENSE OF CHEVROLET CITATION TARGET VEHICLE.





FIGURE C-14. POST-TEST NO. 3, REAR QUARTER PANEL OF CHEVROLET CITATION TARGET VEHICLE.




FIGURE C-15. PRE-TEST NO. 4, VEHICLE CONFIGURATION.



006105

FIGURE C-16. PRE-TEST NO. 4, VEHICLE CONFIGURATION.



006192

FIGURE C-17. POST-TEST NO. 4, OVERALL VIEW OF CHEVROLET CITATION TARGET VEHICLE.




FIGURE C-18. POST-TEST NO. 4, LEFT SIDE DOOR OF CHEVROLET CITATION TARGET VEHICLE.




FIGURE C-19. PRE-TEST NO. 5, VEHICLE CONFIGURATION.




FIGURE C-20. PRE-TEST NO. 5, VEHICLE CONFIGURATION.




FIGURE C-21. POST-TEST NO. 5, OVERALL VIEW OF M5-11 TARGET VEHICLE.




FIGURE C-22. POST-TEST NO. 5, LEFT SIDE DOOR OF M5-11 TARGET VEHICLE.






FIGURE C-23. PRE-TEST NO. 6, VEHICLE CONFIGURATION.



006798

FIGURE C-24. POST-TEST NO. 6, RIGHT SIDE TURN SIGNAL LAMP AND FRAME OF M5-10 VEHICLE.



006803

FIGURE C-25. POST-TEST NO. 7, OVERALL VIEW OF M5-10 VEHICLE.



FIGURE C-26. POST-TEST NO. 7, FRONT VIEW OF M5-10 VEHICLE.



FIGURE C-27. POST-TEST NO. 7, LEFT SIDE HEADLIGHT - M5-10 VEHICLE.

007219



FIGURE C-28. POST-TEST NO. 7, RIGHT SIDE HEADLIGHT - M5-10 VEHICLE.

007225




FIGURE C-29. POST-TEST NO. 7, TURN SIGNAL LAMPS AND MOUNTING FRAME - M5-10 VEHICLE.

TL 242 .G37

Garn, R.

Damageability
Communications

Form DOT F 17
FORMERLY FORM E
Form DOT F 1/20
FORMERLY FORM DO

DOT LIBRARY
00092247